




Instruction Manual

**ZIRCONIA OXYGEN
ANALYZER CONVERTER
(SINGLE-CHANNEL TYPE)**

TYPE: ZRM




CONTENTS

CONTENTS	i
1. OUTLINE	1
1.1 Internal construction	1
1.2 Layout of printed circuit board	2
2. ADJUSTMENT	4
2.1 Instruments required for adjustment	4
2.2 Flow of adjustment	4
3. WIRING CONNECTION AND CHECK.....	5
3.1 Check of wiring connection	5
3.2 Connection when adjustment is being done.....	5
4. POWER ON AND VOLTAGE CHECK	6
4.1 Power ON.....	6
4.2 Voltage check.....	6
5. SET MODE.....	7
5.1 How to change display from “MEASURE” mode to “SET” mode.....	7
5.2 Initial setting	8
6. ADJUSTMENT (ADJ MODE).....	9
6.0 How to move “Adj” mode	9
6.1 Zirconia input signal adjustment (ZERO).....	9
6.2 Zirconia input signal adjustment (SPAN).....	10
6.3 Temperature input adjustment	11
6.4 Current output adjustment (4 to 20mA).....	12
6.5 Adjustment of voltage output (0 to 1V).....	13
6.6 Sub input adjustment.....	15
6.7 Procedure of contact output setting.....	16
7. CALIBRATION BY VOLTAGE GENERATOR	17
7.1 Setting of calibration gas concentration.....	17
7.2 Manual calibration	17
Appendix A. Key operation flow of adjustment mode.....	A-1
Appendix B. Outline of key operation.....	A-2
Appendix C. Circuit diagram.....	A-3


1. OUTLINE

1.1 Internal construction




1.2 Layout of printed circuit board

Layout of printed circuit board (1/2)



Layout of printed circuit board (2/2)



2. ADJUSTMENT

2.1 Instruments required for adjustment

Item	Specification	Quantity
Voltage generator	0 to 2000 mV DC Min. resolution 0.1 mV	1 pc. or 3 pc.
Digital multimeter	Voltage measurement : 0 to 20 V DC Min. resolution 0.1 mV Current measurement : 0 to 200 mA DC Min. resolution 0.01 mA	1 pc.

2.2 Flow of adjustment

Adjustment flow of ZRM is as follows.


- (1) Check of wiring connection
- (2) Power On
- (3) Check of voltage
- (4) "Set" mode
- (5) Individual adjustment
- (6) Calibration by voltage generator

3. WIRING CONNECTION AND CHECK

3.1 Check of wiring connection

Please check the connectors are correctly mounted.


3.2 Connection when adjustment is being done



4. POWER ON AND VOLTAGE CHECK

4.1 Power ON

Turn on the “POWER SWITCH” and adjust LCD contrast by VR1 on display printed circuit board, then LCD display will change as follows.



4.2 Voltage check

Analog/power supply board -----TK4C7182 R3

TP13-TP14	$5 \pm 0.2V$
TP15-TP16	$15 \pm 0.3V$
TP17-TP18	$15 \pm 0.3V$
TP19-TP20	$15 \pm 0.3V$
TP21-TP22	$5 \pm 0.2V$


Display (CPU) unit -----TK4C7179 R2

TP6-TP7	$5 \pm 0.2V$
TP8-TP9	$5 \pm 0.2V$

5. SET MODE

5.1 How to change display from “MEASURE” mode to “SET” mode.

Key Operation procedure



5.2 Initial setting

List 5.1 shows “Initial Set Value” (factory setting).


If any troubles happen during operation, it is recommended that you may check each value with the listed initial set value.

Table 5.1 List of Initial Set Values (factory setting)

Items	Display	Set value
Password	PASSWORD SET	0000
Output range	OUTPUT RANGE	25.0 %O ₂
Averaging time	AVERAGING TIME	002 SEC
Span gas set	SPAN GAS SET	20.6 %O ₂
Zero gas set	ZERO GAS SET	1.01 %O ₂
Meas. wait time	MEAS. WAIT TIME	010 SEC
Auto blow cycle	AUTO BLOW CYCLE	00 H 00 MIN
Blow down time	BLOW DOWN TIME	0 MIN 30 SEC
High alarm	HIGH ALARM	55.0 %O ₂
Low alarm	LOW ALARM	0.01 %O ₂
Output hold	OUTPUT HOLD	NO
D. out select	D. Out Select	DO. 2 MAINTENANCE DO. 1 BLOW DOWN DO. 3 ZERO VALVE DO. 4 SPAN VALVE
Comm. station No.	Station NO.	1
Communication condition	Comm. Select	Boud 9600 Bit 8 Parity NONE Stop 1
Choice of TC	Thermo Couple	R
Detector temp. setting	Temp. Control	800 °C
Sub input select	Sub Input Select	R
A. out select	A. Out Select	4 to 20 mA Note: Factory setting depends on model code. (5th digit “B” ⇒ 4 to 20mA DC) “E” ⇒ 0 to 1V DC)
Auto calibration cycle	AUTO CAL. CYCLE	00 DAY 00 H

6. ADJUSTMENT (ADJ MODE)


6.0 How to move “Adj” mode



After 5.1, the following key operation is required.

Press key 5 times, then display changes to “Adj. mode”.

6.1 Zirconia input signal adjustment (ZERO)



At the initial display of adjustment mode shown on the left, press key.

Press key, when cursor “_” is under “Zr. Input ZERO”

Press or key, and choose range to adjust.

1000mV ⇔ 250mv ⇔ 100mV ⇔ (1000mV)


Then press key.

Input 0mV at terminals No. ⑤ and ⑥, and select “Y” by pressing or key.

Wait for 20 seconds, and then press key.

Adjust other ranges (250mV and 100mV) by same procedure.

6.2 Zirconia input signal adjustment (SPAN)



Select “Zr. Input Span” mode by pressing **SET** key at display shown on the left.

Select range to adjust by **△** or **▽** key.

1000mV ⇔ 250mV ⇔ 100mV ⇔ -50mV
⇔ (1000mV)


Then press **SET** key.

Input actual voltage shown in LCD display at terminals No. ⑤ and ⑥, and select “Y” by pressing **△** or **▽** key.

Wait for 20 seconds, and press **SET** key.

Adjust other ranges (250mV, 100mV and -50mV) by same procedure.

6.3 Temperature input adjustment



Select “TC Input Adj” mode by pressing **SET** key at display shown on the left.

Select “ZERO” by **△** or **▽** key, and then press **SET** key.

Input 0mV at terminals No. ⑦ and ⑧ .

Select “Y” in the display shown on the left.

Wait for 20 seconds, and then press **SET** key.


Select “SPAN” and “Y” by the same procedure as “ZERO” mode.

Input 50mV at terminals No. ⑦ and ⑧ .

Wait for 20 seconds, and then press **SET** key.

6.4 Current output adjustment (4 to 20mA)

Analog output selection



Select “A. Out Select” mode by pressing

SET key at display shown on the left.


Select “4 ~ 20mA” by **△** or **▽** key, and then press **SET** key.

Note : Be sure that positions of jumper pins on analog/power supply board (TK4C7182 R3) are as follows.

①—② <short circuit>

③—④ <short circuit>

Adjustment of current output at 5% point




Select “5” by pressing **△** or **▽** key, and then press **SET** key.

Connect current meter at terminals No. ① and ②, and press **△** or **▽** key so that current meter shows $4.8 \pm 0.05 \text{mA}$.

After adjustment, press **SET** key, and go to adjustment at 100% point.

Adjustment of current output at 100% point




Select “Analog Out Adj” mode, by pressing **SET** key at display shown on the left. Select “100%” by pressing **▲** or **▼** key.

Connect current meter at terminals No. ① and ②, and press **▲** or **▼** key so that current meter shows $20.0 \pm 0.05 \text{mA}$.

After adjustment, press **SET** key.

6.5 Adjustment of voltage output (0 to 1V)



Select “A. Out Select” mode by pressing **SET** key at display shown on the left. Select “0 ~ 1V” by pressing **▲** or **▼** key, and then press **SET** key.

Note : Be sure that positions of jumper pins

on analog/power supply board (TK4C7182 R3) are as follows.

①—③ <short circuit>

②—④ <short circuit>

Adjustment of voltage output at 5% (0 to 1V)

Analog Out Adj. 5% <Up/DOWN>

Select “5%” by pressing or key, and press key.

Connect voltage meter at terminals No. ① and ②, and press or key so that voltage meter shows $50 \pm 0.5 \text{mV}$.

After adjustment, press key.

Adjustment of voltage output at 100% (0 to 1V)

Analog Out Adj. 100% <Up/DOWN>


Select “100%” by pressing or key, and press key.

Connect voltage meter at terminals No. ① and ②, and press or key so that voltage meter shows $1000 \pm 0.5 \text{mV}$.

After adjustment, press key.

6.6 Sub input adjustment

Sub input adjustment (ZERO)




Note : Required only if 6th digit in model code is "B" or "C".

Select "Sub Input Adj" mode by pressing **SET** key at the display shown on the left. Select "Zero" by pressing **△** or **▽** key, and then press **SET** key.

Input 0mV at terminals No. ③ and ④.

Select "Y" by pressing **△** or **▽** key. Wait for 20 seconds, and press **SET** key.

Sub input adjustment (SPAN)




Select "Sub Input Adj" mode by pressing **SET** key at display shown on the left.

Select "SPAN" by pressing **△** or **▽** key and then press **SET** key.

Input 50mV at terminals No. ③ and ④, and select "Y" by pressing **△** or **▽** key. Wait for 20 seconds, and then press **SET** key.

6.7 Procedure of contact output setting

Note : Firstly, move from “Adj” mode to “Set” mode.



Select “D. Out Select” mode, by pressing **SET** key.

Select DO. number by pressing **▲** or **▼** key and press **SET** key.

Select setting item for each D.Out and press **SET** key.

After setting all items, select “EXIT” and press **SET** key.

List 6.1 Factory (initial) setting

Item	LCD display	Terminal No.
DO. 1	BLOW DOWN	⑪ ⑫
DO. 2	MAINTENANCE	⑨ ⑩
DO. 3	ZERO VALVE	⑳ ㉑
DO. 4	SPAN VALVE	㉔ ㉓

List 6.2 Adjustable items

Item	LCD display
NONE	NONE
BLOW	BLOW DOWN
MAINTENANCE	MAINTENANCE
H/L ALARM	H/L ALARM
L ALARM	LOW ALARM
H ALARM	HIGH ALARM
ZERO VALVE	ZERO VALVE
SPAN VALVE	SPAN VALVE
FAULT	FAULT

7. CALIBRATION BY VOLTAGE GENERATOR

7.1 Setting of calibration gas concentration

Note : Firstly, change display to “SET” mode (see page 7).

```
SPAN GAS SET
  20.600 %O2
```

Referring to outline of key operation (see Appendix B), select “Span Gas Set” mode and then input 20.600 %O₂.

```
ZERO GAS SET
  01.010 %O2
```

Referring to outline of key operation (see Appendix B), select “Zero Gas Set” mode and then input 01.010 %O₂.

7.2 Manual calibration

```
MANUAL CAL SPAN
<START? Y>
```

Note : Firstly, change display to “MAINTENANCE MODE” (see page 7).

Referring to outline of key operation (see Appendix B), select “MANUAL CAL SPAN” mode.


Input 0mV at terminals No. ⑤ and ⑥, and then press key so that span calibration will be done.

```
MANUAL CAL ZERO
<START? Y>
```


Referring to outline of key operation (see Appendix B), select “MANUAL CAL ZERO” mode.

Input 66.45mV at terminals No. ⑤ and ⑥, and then press key so that zero calibration will be done.


Appendix A. Key operation flow of adjustment mode




Appendix B. Outline of key operation




Single O₂ Analyzer Display Board (2/2)




Single O₂ Analyzer Analog/Power Supply Unit (1/3)



Single O₂ Analyzer Analog/Power Supply Unit (2/3)



Single O₂ Analyzer Analog/Power Supply Unit (3/3)



Fuji Electric Systems Co., Ltd.

Head Office

Gate City Ohsaki, East Tower, 11-2, Osaki 1-chome,
Shinagawa-ku, Tokyo 141-0032, Japan
<http://www.fesys.co.jp/eng>

Instrumentation Div.

International Sales Dept.

No.1, Fuji-machi, Hino-city, Tokyo 191-8502, Japan
Phone: 81-42-585-6201, 6202 Fax: 81-42-585-6187
<http://www.fic-net.jp/eng>
